



Simplicity LSC Axle

Defect There is a risk of insufficient weld penetration on the arm of the Axle, potentially resulting in a weak and insufficient weld strength.

Hazard The suspension arm may break, causing the Axle to become unstable, and/or a wheel to detach from the Axle.

What to do Consumers should stop using the caravan, trailer, horse float or other vehicle fitted with the Axle and contact Simplicity Axle to arrange for an inspection by an authorised repair agent, and if necessary, repair.

Contact details Production Manager, Simplicity Axles on (03) 9401 4077 Mon-Fri 9am-5pm or Email: <u>suspensioncheck@simplicityaxles.com.au</u>

See productsafety.gov.au for Australian product recall information