Product Safety Recall

Inokim OX Super and Inokim OXO Super Electric Scooters





Sold by electric scooter retailers between 30 December 2020 and 1 July 2021

Defect

Due to a software update, the light module may overheat when the lights are being used. This may cause the scooter's controller or lights to fail and the scooter may shut down.

Hazard

If the scooter's controller or lights fail, or the scooter shuts down, there is an increased risk of an accident resulting in injury or death to the rider or bystanders.

What to do

Consumers should stop riding the scooter and contact Eco Scooters to organise for the scooter to be repaired, free of charge.

Contact details

Consumers can contact Eco Scooters on 1300 140 044 or https://www.ecoscooters.com.au/?id=contact eco scooters

See productsafety.gov.au for Australian product recall information