



Product Safety Recall



Do you own this product?

GPC Asia Pacific — Lower Control Arm Ball Joint

Global branded ball joints for lower control arm supplied as replacement part for aftermarket steering and suspension.

Suited for Toyota Land Cruiser Prado 90/95 series sold between July 1996 – February 2003.

Dates sold: Ball joints sold between 1 May 2022 – 8 September 2023



Why the product is recalled: The supplied bolts used to secure the ball joint of the steering and suspension unit may shear or snap and cause the wheels collapse into the guard.

Hazard: There is a risk of accident, serious injury or death if the bolts shear or snap while the vehicle is used. The risk of incident is increased if the vehicle is used for off-road or 4WD driving.



Consumers should stop using the vehicle for off-road or 4WD driving immediately.

Consumers should take the vehicle to the place where the product was purchased or installed to arrange for an inspection. Consumers will be offered free replacement of the bolts or ball joint if the bolts are affected.



Ask our staff to find out more about the recall, or if consumers cannot return their vehicle to the place of purchase.

recalls@gpcasiapac.com

1300 301 072



Purchased from: Repco Auto Parts, NAPA Auto Parts, Sparesbox

PRA 2023/19955

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information