



# Product Safety Recall

## Do you own this product?



### Fastener (Part Number 942) and accessory rear suspension kits for certain Softail motorcycles (Part Number 54000134 and 54000294)

Fastener (Part Number 942) on certain Model Year 2018 – 2023 Softail motorcycles.

P&A Profile Low Rear Suspension Kit (Part Number 54000134)

or

P&A Tall Rear Shock Kit (Part Number 54000294).

Kits intended for installation on the following Softail motorcycles:

- Part Number 54000134 - Fits 2018 onwards FLHC and FLHCS models.
- Part Number 54000294 - Fits 2018 onwards Softail® models (except FXFB, FXFBS, FLFB and FLFBS).

Dates sold: 24 August 2017 – 30 August 2023



**Why the product is recalled:** The fastener may fracture, potentially allowing the rear shock absorber adjuster to contact the rear tyre.

**Hazard:** There is a risk of serious injury or of an accident occurring if contact from the rear shock adjuster causes damage to the tyre.



1. Consumers should stop using motorcycles with affected rear suspension kits immediately.
2. Contact the nearest Harley-Davidson dealer to schedule an appointment to have their motorcycle repaired free of charge.
3. To find a local dealership, visit <https://www.harley-davidson.com/au/en/tools/find-a-dealer.html>



For more information contact Harley Davidson on +61 2 9886 0600.



Purchased from: Harley-Davidson Authorised Dealers

PRA2023/19913

See [productsafety.gov.au](https://www.productsafety.gov.au) for  
Australian product recall information