

Product Safety Recall

Under Armour UA HOVR™ and FLOW Running Shoes



UA HOVR Machina 3
3024899-001



UA HOVR Machina 3
3024907-001



UA HOVR Machina Off Road
3023892-002



UA HOVR Sonic 5
3024898-001



UA HOVR Sonic 5
3024906-001



UA HOVR Mega 2 Clone
3024479-001



UA HOVR Mega 2 Clone
3024480-001



UA HOVR Infinite 3
3023540-005



UA HOVR Phantom 2 INKNT
3024154-001



UA HOVR Phantom 2 INKN
3024155-001



UA HOVR Phantom 3
3025516-104



UA HOVR Phantom 3
3025517-103



UA HOVR Guardian 3
3023542-001



UA FLOW Velociti SE
3024017-010



UA FLOW Velociti SE
3024016-105



UA FLOW Velociti Wind 2
3024903-500



UA FLOW Velociti Wind 2
3024911-100



UA W FLOW Synchronicity
3024786-003



UA W FLOW Synchronicity
3024786-600



UA W FLOW Synchronicity
3024786-301

Sold at UA Australia, Rebel Sport, Stylerunner, Foot Locker, Wild Earth and Pace Athletic between 22 June 2022 and 24 June 2022

Defect: The shoes were sold without a warning that the right shoe contains a button battery that is sealed within a pod and embedded in the shoe.

Hazard: Consumers may be unaware that the right shoe contains a button battery that is sealed within a pod and embedded in the shoe.

If young children gain access to button batteries and ingest them, they are likely to suffer severe internal burn injuries, which can result in serious injury or death.

Button batteries also pose a choking hazard to young children.

What to do: Consumers should contact UA Australia Pty Ltd via email customerserviceau@underarmour.com to obtain a copy of a warning about the button battery contained in the UA HOVR™ and FLOW running shoes and advice about their consumer guarantee rights under the Australian Consumer Law.

See productsafety.gov.au for
Australian product recall information