



Product Safety Recall

Do you own this product?

Roy Gripske & Sons Pty Ltd – Gravely lawn mowers

Kawasaki general engines with voltage regulator (part no. 21066-0785) installed in select Gravely lawn mowers.



Affected Gravely lawn mower models:

- 992297 - Pro-Turn Mach 1
- 992500 - Pro-Turn 652
- 992501 - Pro-Turn 660
- 992502 - Pro-Turn 672
- 992510 - Pro-Turn 552
- 992511 - Pro-Turn 560
- 992512 - Pro-Turn 572
- 992515 - Pro-Turn Mach 1

Dates sold: 1 April 2021 – 19 December 2023



Why the product is recalled: The voltage regulator in affected Kawasaki general purpose engines, installed in select Gravely lawn mowers, can malfunction. The affected mowers can catch fire at any time, even if the engine is off or not in use.

Hazard: There is risk of serious injury, death and/or damage to property if the voltage regulator catches fire.



Action required:

1. Stop using the affected mower until it has been repaired.
2. Disconnect the negative battery cable and secure it away from the negative battery post. If you are unsure on how to disconnect the battery, see the [battery disconnection instructions](#) or contact your [local Gravely dealer](#).
3. Contact your local Gravely dealer to arrange repair.



For more information contact Roy Gripske & Sons Pty Ltd via email sparesqld@rgs.com.au or phone 1300 363 004 (8:30am to 4:30pm, Monday to Friday).



Purchased from: [Gravely dealers](#)

PRA 2024/20128

See productsafety.gov.au for
Australian product recall information