

# Product Safety Recall



## **Nikon SB-103 Nikonos Speedlight**

Sold at Teds between June 1984 and July 1994

**Defect** in some extremely rare cases, the front of the flash head may pop out, resulting in a burst incident.

**Hazard** the batteries may emit hydrogen gas (for example, if NiCd batteries with differing charge levels are used). When this gas mixed with the air inside the SB-103 and the SB-103 was fired, spark generated by the flash head could cause the front of the flash head to pop out, resulting in a burst incident.

**What to do** Consumers should stop using the product and contact Nikon Australia. Nikon Australia will purchase the product from consumers (incl. freight).

**Contact details** you can contact Nikon Australia by phoning 1300 401 200 Mon-Fri 9am to 5pm, by emailing [Service.Nau@nikon.com](mailto:Service.Nau@nikon.com) or go to [www.nikon.com.au](http://www.nikon.com.au).

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**