

Product Safety Recall

Inokim Quick4 Electric Scooter



Sold by bicycle and scooter stores
between 15 August 2020 and 20 July 2021

Defect The adjustable T-bar on steering stem may crack or fracture if the bolt is overtightened or if the scooter is ridden in rough conditions, such as off-road, over kerbs or speed bumps.

Hazard If the T-bar stem cracks or fractures while the scooter is being ridden, there is an increased risk of an accident or serious injury or death to the rider.

What to do Consumers should stop riding the scooter and contact Eco Scooters to organise for the scooter to be repaired, free of charge.

Contact details Consumers can contact Eco Scooters on 1300 140 044 or https://www.ecoscooters.com.au/?id=contact_eco_scooters

See productsafety.gov.au for
Australian product recall information