

Product Safety Recall

Venco Direct Drive & Venco Number 7 Pottery Wheels



Supplied by GP & GF Hilll Pty Ltd
Venco Direct Drive between 2006 and 2019
Venco Number 7 between 1999 and 2007

Defect Hazardous voltage could reach a conductive part of the foot pedal if wires inside the foot pedal become detached from the potentiometer, or corroded as a result of moisture and then touch a metal rod at the top of the pedal. Wires can also twist and potentially break if the nut at the back of the pedal becomes loose.

Hazard Risk of electric shock.

What to do Immediately stop using the product, contact a Venco Agent to arrange inspection by a licensed electrical contractor and repair, if required.

To find a Venco agent visit <https://venco.com.au/agents-2/>

Contact Details For further information contact Venco at info@venco.com.au

See productsafety.gov.au for
Australian product recall information