

Product Safety Recall



HOLEC DUMECO SWITCH DISCONNECTORS

Models Affected: DMV250 and DMV400 fitted to CUTLER-HAMMER and EATON LV switchboards manufactured from May 2001 to 16th March 2009.

Identification: LV Distribution boards type QCC, DCC, ECHIDNA, EWQ, EWD, and "Plus" variants, that are fitted with a 250A or 400A main isolator branded HOLEC or EATON with a clear cover and a black lever-type rotary handle (as shown in the above photographs)

The Hazard: The handle may fail to operate as intended under normal use. This could lead to an operator suffering an electrical shock after removing the switchboard escutcheon plate, if normal safety procedures are not followed to confirm the electrical supply has been isolated.

Action Required: Customers who believe they may have an affected product should contact Eaton by email to auhandles@eaton.com or should visit the website www.eatonelectrical.com.au/handles, to obtain full information on methods of identifying the installed products and to arrange a handle replacement kit where required.

See www.recalls.gov.au for Australian Product Recall Information