Product Safety Recall



















KOO 2L Hot Water Bottle Supplied by Spotlight from 19 May 2016 to 13 July 2020

Defect: The hot water bottles may not meet the performance

requirements of the 'Trade Practices (Consumer Product Safety

Standard) (Hot Water Bottles) Regulations 2008'.

Stopper could leak or seams could split.

Hazard: Hot water may leak from the hot water bottle, increasing the risk

of burns or serious injury.

What to do: Consumers should immediately stop using the product and

return to Spotlight for a refund of the purchase price.

Contact Details: Customers seeking a refund should contact Spotlight on

1300 305 405 or visit www.spotlightstores.com/contact-us.

See productsafety.gov.au for Australian product recall information