

Product Safety Recall

Nissan R52 Pathfinder Towbar Suitable for installation on MY2017-2020 Nissan R52 Pathfinder vehicles



Batch number 29 18
Sold by Nissan Australia Dealers
between 1 December 2016 and 31 December 2020

Defect Due to a manufacturing issue, there may be weld separation on the right hand side of the towbar attachment bracket. As a result, the towbar cross member and bracket could separate and the towbar could detach from the vehicle.

Hazard If the towbar detaches from the vehicle while towing, this will causing a loss of control of the trailer and increase the risk of an accident that may result in injury or death of vehicle occupants and/or other road users.

What to do When parts become available in mid-May 2021, consumers will be advised to contact their Nissan Dealer to organise for the inspection of the towbar compliance plate to determine whether their towbar is affected by this recall. If affected, a replacement towbar will be provided, free of charge.

Contact details Consumers can contact the Nissan Customer Service Centre on 1800 035 035 (Monday to Friday, 8:30am to 6:00pm AEST) or find their nearest dealership at <https://www.nissan.com.au/find-a-dealer>

**See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information**