

Product Safety Recall



YAMAHA MY22 YXM700 (Viking) ROV Rear Brake Line

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
YXM700E	2022	AMA5E	101788	101837

Sold by authorised Yamaha dealers between 1 March 2022 to 30 April 2022

Defect

The retaining clamp for the rear brake pipe was installed incorrectly.

Hazard

Incorrect installation of the rear brake pipe clamp, may result in the rear brake pipe contacting the front drive shaft and damaging the brake pipe during operation, resulting in brake failure. Brake failure during use of a vehicle may cause an accident, resulting in serious injury or death of vehicle occupants or bystanders.

What to do

Consumers should contact your local Yamaha Dealer to arrange for an inspection and repair, if required, free of charge.

Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.com.au>

For more information, contact Yamaha Motor Australia on 1300 277 137.

Australian Importer/Distributor
Yamaha Motor Australia
489-493 Victoria Street, Wetherill Park
NSW, Australia

See www.productsafety.gov.au for
Australian product recall information