



Product Safety Recall



Do you own this product?

ARB tyre pressure monitoring system (TPMS) sensor

internal and external sensors

Sold in in various kits:

- 819103 - TPMS INTERNAL 5 SENSOR SYSTEM
- 819103A - TPMS INTERNAL 5 SENSOR SYSTEM
- 819104 - TPMS EXTERNAL 4 SENSOR SYSTEM
- 819106 - TPMS INTERNAL 2 SENSOR SYSTEM
- 819106A - TPMS INTERNAL 2 SENSOR SYSTEM
- 819107 - TPMS EXTERNAL 2 SENSOR SYSTEM
- 820002 - INTERNAL SENSOR SINGLE

Dates sold: 22 June 2022 – 11 March 2024

Why the product is recalled: The product does not comply with [the mandatory information standard for products containing button/coin batteries](#).



The product does not include the required warning information.

Hazard: There is a risk of choking, severe internal burn injuries or death to young children if they gain access to the button/coin batteries and swallow or place them inside their body.

Severe or fatal injuries can happen in 2 hours or less.

Consumers may not be aware the product contains button batteries.



1. Consumers should keep the product out of reach of children.
2. Consumers can contact Vision via email at: productrecall@visionautotech.co.th to get a copy of the warning information.
3. Consumers can also register their details by contacting ARB through their website: www.arb.com.au/tpms-recall



Purchased from: Various 4wd accessory stores

See detailed traders list on www.productsafety.gov.au

PRA2024/20125

See productsafety.gov.au for
Australian product recall information