

# Product Safety Recall

## Do you own this product?




Trek Bicycle Corporation (Australia) Pty Ltd —  
Certain Promax Solve DSK 925 and Promax F1 DSK  
927 hydraulic disc brakes fitted on certain model  
year 2021, 2022 and 2023 Trek bicycles

Hydraulic disc brakes built with first generation barbs  
and fitted to the following year bicycle models:

2021: FX 2, Verve 3, Verve + 3

2022: FX 2, FX3, Verve 3, Verve + 3, FX Sport 4, FX  
Sport 5, FX Sport 6, Dual Sport 2 and Dual Sport 3

2023: FX 2, FX 3, FX Sport 4, FX Sport 5, FX Sport 6,  
Dual Sport + 2 and FX + 2



Brakes built with the second and third generation barbs  
are not affected.

Dates sold: 1 September 2021 – 16 June 2023



**Why the product is recalled:** The hoses on affected brakes may eject  
or pull out from the brake lever and lead to improper engagement of the  
brake hose to the brake lever.

**Hazard:** Risk of serious injury following loss of brake function and control  
while riding.

Consumers should check to see if their bicycle is affected by visiting the  
[serial number look-up tool](#) or contacting Trek Australia.



If affected, immediately stop using the bicycle and take the bicycle to a  
Trek retailer for inspection and, if required, repair.

Affected bicycles with affected brakes will be fitted with replacement  
parts.



For further information, contact Trek Australia by phone on 02 6173 2400  
or email [customerservice\\_australia@trekbikes.com](mailto:customerservice_australia@trekbikes.com).



Purchased from: Trek retailers

PRA 2023/19852

See [productsafety.gov.au](https://www.productsafety.gov.au) for  
Australian product recall information