

Product Safety Recall



DESCRIPTION: RD 40 Combination Respiratory Protection Filters

Part No	Description	Affected Serial No
6738797	Combi filter 1140 A2B2E2K2HgP3 R D	ARRF-F001 & ARRE-F001
6738801	1140 A1B2E2K1HgNO P3 R D/CO 20 P3 R D	ARRE-F001 & ARRD-F004

These filters are used with full face masks to protect against various hazardous gases, vapours and particles.

DEFECT: Some Dräger particle filters used in the combination respiratory protection filters do not provide the required particle filtration efficiency.
The toxic gas filtration efficiency of the activated carbon is not affected.

HAZARD: Reduced particle filtration efficiency can result in users inhaling harmful particles. Users may not be able to identify reduced efficiency by looking at the product or during use.

Increased inhalation of particles can lead to irritation of the airways. In the longer term this can lead to serious adverse respiratory health effects, depending on the particle, concentration levels, and the duration of use.

WHAT TO DO: Users should stop using the filter immediately. Consumers should check if the model and serial number of their filter is affected. Consumers should contact Draeger to arrange for the filter to be returned for a replacement filter, free of charge.

If the filter has been used, consumers should also notify Draeger and they will provide a form to document the exposure to the user.

Consumers who have affected filters can contact Draeger via email at quality.australia@draeger.com or phone 1800 372 437. Consumers will return affected filters to

Draeger Australia Pty Ltd
Attn. Quality Department
2 Redwood Drive
Notting Hill VIC 3168

**See productsafety.gov.au for
Australian product recall information**