
## Product Safety Recall IKEA Pty Ltd — LETTAN mirror





This recall was updated on 12 September 2023 to include additional mirrors

Product description: IKEA LETTAN glass mirror sold with fittings to be fitted to the wall.

Affected mirrors have a date stamp on the back:

- Before and including 2105 (YYWW) (21 stands for the year and 05 stands for the week the product was produced)
- Before and including 2325 (YYWW) and supplier number 21944

The supplier number and date stamp can be found on the label on the rear of the mirror.

**Defect:** The fittings that attach LETTAN mirrors to the wall may fail causing the mirrors to fall and shatter.

Hazard: Shattered glass from the LETTAN mirrors has caused laceration injuries.

**What to do:** Customers should remove LETTAN mirrors from walls immediately and contact IKEA using the details below to order replacement fittings.

**Contact details:** For more information, please visit <a href="www.IKEA.com.au/recalls">www.IKEA.com.au/recalls</a> or phone IKEA on:

ACT/NSW - 02 8020 6641 Queensland - 07 3380 6800 Victoria/Tasmania - 03 8523 2154 Perth - 08 8234 3944 Adelaide - 08 8234 3333

> See productsafety.gov.au for Australian product recall information

\_\_\_\_